CAMBRIDGE INTERNATIONAL EXAMINATIONS

International General Certificate of Secondary Education

MARK SCHEME for the May/June 2014 series

0445 DESIGN AND TECHNOLOGY

0445/31

Paper 3 (Resistant Materials), maximum raw mark 50

This mark scheme is published as an aid to teachers and candidates, to indicate the requirements of the examination. It shows the basis on which Examiners were instructed to award marks. It does not indicate the details of the discussions that took place at an Examiners' meeting before marking began, which would have considered the acceptability of alternative answers.

Mark schemes should be read in conjunction with the question paper and the Principal Examiner Report for Teachers.

Cambridge will not enter into discussions about these mark schemes.

Cambridge is publishing the mark schemes for the May/June 2014 series for most IGCSE, GCE Advanced Level and Advanced Subsidiary Level components and some Ordinary Level components.



	Page 2	Mark Scheme	Syllabus	Paper	
	*	IGCSE – May/June 2014	0445	31	
		Section A			
1	(a) Aluminiu	m			[1]
	(b) Lightwei	ght, light, corrosion resistant, good strength-we	eight ratio, low density		[1]
2	-	pins in line, blade facing correct way, wood he damaged, blade is sharp	eld securely, blade tight,	(2×1)	[2]
3	(a) Accuracy	y of drawing: two parallel edges for 2 marks		(0–2)	[2]
	(b) Safe edg	ge correctly labelled			[1]

4

Tool	Name	Specific use	
	Guillotine, bench shears	Cutting thin metal/small section metal	
Star	Jack plane	Preparation of material, quick removal of waste material	

5	(a) Vacuum forming, injection moulding	[1]
	(b) Release from mould	[1]
	(c) To add strength, rigidity	[1]
6	2 measurements indicated: floor to behind knee, behind knee to backside, backside to lumber area (2×1)	[2]
7	1 mm thick mild steel: scriber, odd legs, scribing gauge, scribing block	
	3 mm thick acrylic: chinagraph pencil, marker pen, felt-tip, leave backing paper on or apply masking tape and use pen or pencil	[2]
8	Sheet metal shown between folding bars(1)Folding bars shown in vice(1)Use of mallet or hammer and scrap wood(1)	[3]

	Page 3	Mark Scheme	Syllabus	Paper	
		IGCSE – May/June 2014	0445	31	
9	(a) Soft sold	er			[1]
	(b) Tinplate	work, plumbing			[1]
10		ges of moulded polypropylene include: weather re noved around, comfortable armrests, will not rust, t be qualified	-	(2×1)	[2]

	Page 4			Mark Scheme	Syllabus	Paper	
				IGCSE – May/June 2014	0445	31	
				Section B			
11	(a)	Awa Mus 1 do Suita	ird 0- t be i wel o able	joints include: M&T, halving, bridle, dowel –3 dependent upon accuracy of sketch in correct orientation otherwise max. 2 marks only shown = 2 marks max. joint named to match sketch accept tenon or mortise on their own]		(0–3) (1)	[4]
	(b)		gene [Do r	ety of glues include: trade names such as Evo-Stik F eric synthetic resin, PVA not accept epoxy resin] e to set to correspond with named glue: PVA 1–4 ho			irs
		(ii)	Sasł	n cramps			[1]
			mea	ecks include: square, flat, joints pulled together, rem sure diagonals, use of scrap wood to spread pressu nped straight, clamps not over tightened, clamps tigh	re or prevent dam		[2]
	(c)	Som	ne for	drilling machine shown rm of 'wedge' to provide 20° angle or rotate table an ce secured/clamped	d lock	(1) (1) (1)	[3]
	(d)	Male	e anc	rm of base I female formers/rods of retention		(1) (0–2) (1)	
		OR					
		Rete	entior	d female formers n at start of bend of force		(0–2) (1) (1)	[4]
	(e)	Use	of gl	o to 3 marks max. for practical method that is hidden lued blocks/KD fittings/visible bracket/corner plates r -1 for details of sizes and materials		(0–3) (0–1)	[4]
	(f)		rd 1	mark for recognition that frame needs to be in 4 sep D fittings/dowel/screws to connect separate pats	arate parts	(0–1) (0–2)	
			rd 1	mark for recognition that rods need to be in 3 separa of connecting 3 separate parts for each rod	ate parts	(0–1) (0–1)	[5]

	Page 5			Mark Scheme	Syllabus	Paper	
				IGCSE – May/June 2014	0445	31	
12	(a)			s include: check sizes, appearance, will it work, ch od [Do not accept references to a template]	eaper than making it	(2×1)	[2]
	(b)			method: dowel, M&T, added metal or wood suppor- -3 dependent on technical accuracy (0–3)	rt on surface of base	(0–3)	
		1 do Use	owel of so	o to max. 3 marks for support shown into mortise w only = max. 2 marks crews or nails from underneath = max. 2 marks screw = max. 1 mark	/ithout shoulders		
				method to correspond to sketch		(1)	[4]
	(c)	(i)	Quic	ker, more accurate, cuts fibres of wood, cannot be	rubbed off	(2×1)	[2]
		• •		eptable methods: of plane, hand-powered router, band saw table tilt	ed at 45° angle	(1)	
				d secured for plane and hand-powered router d saw requires fence/guide		(1)	
			Tech	nnical accuracy of named tools and equipment		(1)	[3]

(d)

Process	Tools/equipment used
Mark out	Pencil, rule, sliding bevel, marking knife, mitre square
Saw off waste	Tenon saw, coping saw, various machine saws including Hegner, band saw, jig saw
Make sawn edges smooth	Sanding disc, file, chisel, plane, glasspaper/sandpaper

(3×1) **[3]**

(e)	(i)	Panel pins, oval wire, oval nail, round nail, round head, round wire, lost head		[1]
	(ii)	PVA, synthetic resin, contact [impact] ,accept trade names such as Resin W. [Do not accept epoxy resin, animal or scotch glue]		[1]
	(iii)	Easier to clean, remove debris, allows water to escape		[1]
(f)	too woo met awa awa	blems involve weather/climate: hot or cold, too wet or dry, fungal/insect attack, windy conditions ods can shrink or expand, rot tals can rust, plastics can fade ard 1 mark for each sensible problem identified ard 1 mark for each method to overcome problem . painted to protect, choice of material for specific environment	(2×1) (2×1)	[4]

s.com

		wv	vw.xtrap	ape
Page 6	Mark Scheme	Syllabus	Paper	
	IGCSE – May/June 2014	0445	31	
Reinfor [Do not	D [or support] shaped to fit under roof ced using block or strip of wood accept screwing of roof to shaped end of support] of materials and constructions used		(1) (1) (0–2)	[4]
	200			
(a)	1 MARK FOR CUT OUT			
()	ard 1 mark for each cut shown above orrect orientation = 0 marks		(5×1)	[5]
• •	icker, more accurate, repetitive accuracy mplate can be used as a 2D model		(2×1)	[2]
	etch to show work low in the vice to prevent it crackir ded notes to describe how problem is overcome	ng	(0–2) (0–1)	[3]
	ard work piece clamped in position/use of machine v ard work piece supported underneath	rice	(1) (1)	

- Award work piece supported underneath (1) Award slow speed of drill/correct cutting angle/pilot drills (1) [3]
- (c) Use of wet and dry paper, polishing wheel, mop and compound/polish Award any 2 items of equipment described (2×1) [2]
- (d) Heated over a line bender/strip heater/hot air gun to become soft (1)Use of former or round bar (1) Softened acrylic draped over former/round bar and held (1) Technical accuracy **(**1) [4]
- (e) Practical solution/ concept (0-3)Details of sizes and constructions (0-3)[Materials used must be appropriate for 4 mm thick acrylic otherwise 0 marks] [6]